

## **COMPLAINT INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	John McCutcheon
Inspection Date:	Wednesday, August 15, 2018	Project Contact:	Brian Clauto, Tracy Hilbun
Spread:	Spread I	Weather (Wet/Dry/Rain):	Dry

	•				•	
STA	GE OF CONSTRUCTION: (Check all that apply)					
$\boxtimes$	Clearing Rough Grading Trench Exca	Rough Grading Trench Excavation				Pipe Assembly, Testing & Installation
	ckfilling and Grade Restoration Final Grading & Stabilization					Other:
		Yes	No	N/A		
1	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	$\boxtimes$				
2	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	$\boxtimes$				
3	Areas of offsite sediment deposition were observed?		$\boxtimes$			
Co	omments: This report is for an inspection at Bent Mountain in Roanoke Cou	nty or	n Bot	tom C	reek F	Road in response to a complaint of a
ро	rtable toilet located near a stream.					
	1. Portable toilet observed to be located well-away from stream.					
<u>Dea</u>	dline: N/A					
cons	recommended corrective action deadline date applies to all conditions noted on this re titute non-compliance and/or corrective actions are not completed by the deadline, other tring compliance on the above project.					
	pector Signature:				Б.	0.45.40
Insp	pector Signature:				Date	e: <u>8-15-18</u>



## FIELD INSPECTION PHOTO LOG

Project Name: <u>Mountain Valley Pipeline</u> Date:Wednesday, August 15, 2018

